




Part of WAREMA GROUP




## Services Price List


2024

Price list is applicable as of 01.06.2024  
edition 1/2024


## 16/25 HORIZONTAL BLINDS

	Service	Unit of measurement	Price	Comments
	Retrofitting the blind with side guide	pcs	26 EUR	
	Swapping control sides	pcs	26 EUR	
	Rail replacement	pcs	26 EUR	
	Replacement of the stack of slats	pcs	26 EUR	+ the cost of replacement parts
	Replacement of cords and ladders	pcs	26 EUR	
	Repairing the blind	pcs	individual pricing	
	Shortening the blind	pcs	26 EUR	
	Lengthening the blind	pcs	26 EUR	

## 25 MM WOODEN BLIND

	Service	Unit of measurement	Price	Comments
	Retrofitting the blind with side guide	pcs	41 EUR	
	Swapping control sides	pcs	41 EUR	
	Replacement of cords and ladders	pcs	41 EUR	+ the cost of replacement parts
	Repairing the blind	pcs	individual pricing	
	Shortening the blind	pcs	41 EUR	
	Lengthening the blind	pcs	41 EUR	

## 50 MM ALUMINIUM BLIND

	Service	Unit of measurement	Price	Comments
	Shortening the blind	pcs	41 EUR	
	Lengthening the blind	pcs	41 EUR	
	Repairing the blind	pcs	individual pricing	+ the cost of replacement parts
	Swapping control sides	pcs	41 EUR	
	Replacement of cords and ladders	pcs	41 EUR	
	Retrofitting the blind with side guide	pcs	41 EUR	

## 50 MM WOODEN BLIND

	Service	Unit of measurement	Price	Comments
	Narrowing <b>wooden blind</b>	pcs	41 EUR	Symmetrically, max 3 cm on one side; blind without side guide
			41 EUR	Symmetrically, max 1 cm on one side; blind with side guide
	Shortening the blind	pcs	41 EUR	
	Lengthening the blind	pcs	41 EUR	
	Repairing the blind	pcs	individual pricing	+ the cost of replacement parts
	Swapping control sides	pcs	41 EUR	
	Replacement of cords and ladders	pcs	41 EUR	
	Retrofitting the blind with side guide	pcs	41 EUR	

## VENUS HORIZONTAL BLINDS

	Service	Unit of measurement	Price	Comments
	Shortening the blind	pcs	26 EUR	
	Lengthening the blind	pcs	26 EUR	
	Changing the colour of accessories	pcs	26 EUR	
	Replacing lifting tapes + ladders	pcs	26 EUR	+ the cost of replacement parts
	Repairing the blind	pcs	individual pricing	
	Swapping control sides – Venus	pcs	26 EUR	
	Swapping control sides – Venus Standard	pcs	26 EUR	


## RM ROLLER BLINDS / FANTAZJA

	Service	Unit of measurement	Price	Comments
	Fabric replacement	pcs	21 EUR	+ the cost of fabric
	Roller blind / fabric narrowing	pcs	21 EUR	more than 0,5 cm
			21 EUR	less than 0,5 cm + the cost of fabric
	Roller blind / fabric shortening	pcs	21 EUR	
	Changing the colour of accessories – Fantazja	pcs	21 EUR	+ the cost of replacement parts
	Changing the colour of accessories – RM roller blinds	pcs	21 EUR	


## GEMI

	Service	Unit of measurement	Price	Comments
	Fabric replacement	pcs	30 EUR	+ the cost of fabric
	Roller blind / fabric narrowing	pcs	30 EUR	more than 0,5 cm
			30 EUR	less than 0,5 cm + the cost of fabric
	Roller blind / fabric shortening	pcs	30 EUR	+ the cost of replacement parts
	Changing the colour of accessories – GEMI	pcs	30 EUR	


## IMPRESJA ROLLER BLINDS

	Service	Unit of measurement	Price	Comments
	Fabric replacement	pcs	21 EUR	+ the cost of fabric
	Roller blind / fabric narrowing	pcs	21 EUR	more than 1 cm
			21 EUR	less than 1 cm + the cost of fabric
	Roller blind / fabric shortening	pcs	21 EUR	


## PLEATED BLINDS

	Service	Unit of measurement	Price	Comments
	Fabric replacement	pcs	21 EUR	+ the cost of fabric
	Pleated blind shortening	pcs	21 EUR	
	Narrowing EV/VS/F/PL/VX pleated blind	pcs	21 EUR	up to 2 cm or more than 5 cm only
	Narrowing DF 10/20/30 pleated blind	pcs	21 EUR	more than 5 cm only
	Replacing cords and wires	pcs	21 EUR	+ the cost of cords and wires
	Changing the colour of accessories	pcs	21 EUR	+ the cost of accessories


## VERTICAL BLINDS

	Service	Unit of measurement	Price	Comments
	Head rail shortening	pcs	21 EUR	
	Link runners replacement	pcs	21 EUR	+ the cost of replacement parts
	Replacing link runners + mechanism	pcs	21 EUR	
	Shortening the slats	pcs	3 EUR	


## ROMAN BLINDS, RVS

	Individual pricing			
-------------------------------------------------------------------------------------	--------------------	--	--	--


**FRAMED INSECT SCREENS**

	Service	Unit of measurement	Price	Comments
	Mesh replacement	pcs	13 EUR	+ the cost of mesh
	PVC corner joints replacement	pcs	16 EUR	
	Changing the width/height (internal corner min. 90 mm, PVC corner min 1 mm)	pcs	19 EUR	
	Changing the width/height – PVC corner	pcs	19 EUR	


**ROLLER INSECT SCREENS**

	Service	Unit of measurement	Price	Comments
	Mesh and tube replacement	pcs	23 EUR	+ the cost of replacing components
	Changing the width	pcs	30 EUR	
	Spring mechanism replacement	pcs	30 EUR	


**SLIDING INSECT SCREEN FOR DOORS / HINGED INSECT SCREEN DOORS**

	Service	Unit of measurement	Price	Comments
	Mesh replacement	pcs	24 EUR	+ the cost of mesh
	Changing the width/height (min. 90 mm)	pcs	44 EUR	
	Cross bar replacement	pcs	29 EUR	


**PLEATED INSECT SCREENS**

	Service	Unit of measurement	Price	Comments
	Mesh replacement	pcs	46 EUR	+ the cost of mesh
	Steel tape replacement	pcs	23 EUR	+ the cost of tape
	Changing the width/height	pcs	53 EUR	


## ROLLER SHUTTERS

	Service	Unit of measurement	Price	Comments
	Changing the width	pcs	36 EUR	+ the cost of replacement parts
	Changing the height	pcs	29 EUR	
	Motor replacement	pcs	35 EUR	
	Replacing the lock on the roller shutter curtain	pcs	24 EUR	

## EXTERNAL VENETIAN BLINDS

	Service	Unit of measurement	Price	Comments
	Changing the height	pcs	94 EUR	+ the cost of replacement parts
	Replacing ladders/ lifting tapes	pcs	75 EUR	
	Replacing guide pins (PVC only)	pcs	16 EUR	
	Motor replacement	pcs	28 EUR	
	Slats replacement	pcs	46 EUR	

## SCREEN external roller blind

	Service	Unit of measurement	Price	Comments
	Changing the width	pcs	64 EUR	+ the cost of replacement parts
	Changing the height	pcs	53 EUR	
	Motor replacement	pcs	28 EUR	
	Fabric replacement	pcs	38 EUR	

## NON-STANDARD SERVICES

individual pricing



---

Part of WAREMA GROUP

---

Anwis sp. z o.o.  
PL, 87-800 Włocławek, Smocza 16/18  
tel. +48 54 412 88 00, fax +48 54 412 88 26  
[www.anwis.pl](http://www.anwis.pl)